



MEYLE No. 300 333 1111/HD
Reference No. 33 31 1 094 036



Subframe mount

to fit

BMW E39



as OE



Problem

Leakage of hydro fluid due to high dynamic strain and small bonding surface

Effect

- Rattling from the rear axle and an overall decline of the handling of the vehicle
- Reduced driving comfort



Solution



Hydro mount replaced by an optimised full-rubber mount with a larger bonding surface

Advantage

No leakage possible and significant longer lifetime without restriction of driving comfort